### § 200.800

## Subpart O—Lead-Based Paint Poisoning Prevention

SOURCE: 64 FR 50224, Sept. 15, 1999, unless otherwise noted.

#### § 200.800 Lead-based paint.

The Lead-Based Paint Poisoning Prevention Act (42 U.S.C. 4821–4846), the Residential Lead-Based Paint Hazard Reduction Act of 1992 (42 U.S.C. 4851–4856), and implementing regulations at part 35, subparts A, B, F, G, I, and R of this title, apply to activities under these programs, except for single family mortgage insurance and guarantee programs. Sections 200.805 and 200.810 apply to single family mortgage insurance and guarantee programs administered by HUD.

### § 200.805 Definitions.

Applicable surface. All intact and nonintact interior and exterior painted surfaces of a residential structure.

Defective paint surface. Paint on applicable surfaces that is cracking, scaling, chipping, peeling or loose.

Lead-based paint surface. A paint surface, whether or not defective, identified as having a lead content greater than or equal to 1 mg/cm<sup>2</sup>.

### § 200.810 Single family insurance and coinsurance.

- (a) General. (1) The requirements of this section apply to any one-to four-family dwelling which was constructed before 1978 and is the subject of an application for mortgage insurance under section 203(b) or other sections of the National Housing Act relating to the insurance or coinsurance of mortgages on one-to-four-family dwellings. Such other sections include:
  - (i) Section 244 (coinsurance);
- (ii) Section 213 (cooperative housing insurance):
- (iii) Section 220 (rehabilitation and neighborhood conservation housing insurance):
- (iv) Section 221 (housing for moderate income and displaced families);
- (v) Section 222 (mortgagor insurance for servicemen):
- (vi) Section 809 (armed services housing for civilian employees);
- (vii) Section 810 (armed services housing in impacted areas);

- (viii) Section 234 (mortgage insurance for condominiums);
- (ix) Section 235 (mortgage assistance payments for home ownership and project rehabilitation);
- (x) Section 237 (special mortgage insurance for low and moderate income families); and
- (xi) Section 240 (mortgage insurance on loans for purchase of fee simple title from lessors).
  - (2) [Reserved]
- (3) Applications for insurance in connection with a refinancing transaction where an appraisal is not required under the applicable procedures established by the Commissioner are excluded from the coverage of this section. Any housing assisted under the programs set out in this section for which no new activity is applied for or required is not covered by this section.
- (b) *Appraisal*. The appraiser shall, when appraising a dwelling constructed prior to 1978, inspect the dwelling for defective paint surfaces.
- (c) Treatment of defective paint surfaces. For defective paint surfaces, treatment shall be provided to defective areas. Treatment of hazards shall consist of covering or removing defective paint surfaces. Covering may be accomplished by such means as adding a layer of wallboard to the wall surface. Depending on the wall condition, wallcoverings which are permanently attached may be used. Covering or replacing trim surfaces is also permitted. Paint removal may be accomplished by such methods as scraping, heat treatment (infra-red or coil type heat guns) or chemicals. Machine sanding and use of propane or gasoline torches (openflame methods) are not permitted. Washing and repainting without thorough removal or covering does not constitute adequate treatment. In the case of defective paint spots, scraping and repainting the defective area is considered adequate treatment. Treatment of a defective paint surface is not required if such a surface is found to not be a lead-based paint surface by a leadbased paint inspector certified pursuant to procedures of the U.S. Environmental Protection Agency at 40 CFR part 745.

(d) Home equity conversion mortgage insurance. The requirements of this section, as modified by the following sentence, apply to a dwelling which is the subject of an application for mortgage insurance under section 255 of the National Housing Act (home equity conversion insurance) unless the mortgagor provides the certification described in §206.45(d) of this title. The defective paint surface may be treated after the mortgage is endorsed for insurance, provided that the defective paint surface is treated as expeditiously as possible in accordance with the repair work provisions contained in §206.47 of this title.

[64 FR 50224, Sept. 15, 1999, as amended at 69 FR 34275, June 21, 2004]

# Subpart P—Physical Condition of Multifamily Properties

Source: 65 FR 77240, Dec. 8, 2000, unless otherwise noted.

### § 200.850 Purpose.

The purpose of this subpart is to establish the physical conditions standards and physical inspection requirements that are applicable to certain multifamily housing properties.

### § 200.853 Applicability.

This subpart applies to:

- (a) Housing assisted by HUD under the following programs:
- (1) All Section 8 project-based assistance. "Project-based assistance" means Section 8 assistance that is attached to the structure (see 24 CFR 982.1(b)(1) regarding the distinction between "project-based" and "tenant-based" assistance);
- (2) Section 202 Program of Supportive Housing for the Elderly (Capital Advances);
- (3) Section 811 Program of Supportive Housing for Persons with Disabilities (Capital Advances); and
- (4) Section 202 loan program for projects for the elderly and handicapped (including 202/8 projects and 202/162 projects).
- (b) Housing with mortgages insured or held by HUD, or housing that is receiving insurance from HUD, under the following authorities:

- (1) Section 207 of the National Housing Act (NHA) (12 U.S.C. 1701 *et seq.*) (Rental Housing Insurance);
- (2) Section 213 of the NHA (Cooperative Housing Insurance);
- (3) Section 220 of the NHA (Rehabilitation and Neighborhood Conservation Housing Insurance);
- (4) Section 221(d)(3) of the NHA (Market Interest Rate (MIR) Program);
- (5) Section 221(d)(3) and (5) of the NHA (Below Market Interest Rate (BMIR) Program);
- (6) Section 221(d)(4) of the NHA (Housing for Moderate Income and Displaced Families);
- (7) Section 231 of the NHA (Housing for Elderly Persons);
- (8) Section 232 of the NHA (Mortgage Insurance for Nursing Homes, Intermediate Care Facilities, Assisted Living Facilities, Board and Care Homes);
- (9) Section 234(d) of the NHA (Rental) (Mortgage Insurance for Condominiums):
- (10) Section 236 of the NHA (Rental and Cooperative Housing for Lower Income Families);
- (11) Section 241 of the NHA (Supplemental Loans for Multifamily Projects). (Where, however, the primary mortgage of a Section 241 property is insured or assisted by HUD under a program covered in this part, the coverage by two HUD programs does not trigger two inspections); and
- (12) Section 542(c) of the Housing and Community Development Act of 1992 (12 U.S.C. 1707 note) (Housing Finance Agency Risk Sharing Program).

# § 200.855 Physical condition standards and physical inspection requirements.

- (a) Applicable standards and requirements. The physical condition standards and physical inspection requirements in 24 CFR part 5, subpart G, are applicable to the properties assisted or insured that are listed in §200.853.
- (b) Entity responsible for inspection of property. The regulations that govern the programs listed in §200.853, or regulatory agreements or contracts, identify the entity responsible for conducting the physical inspection of the property which is HUD, the lender or the owner. For properties with more than one HUD insured loan, only the